



ASSEMBLY INSTRUCTION

MODEL:MARE LN6916 3211EE



HARDWARE LIST

NO	A	B	C	D	E	F	G	H	I	J
DESC										
QTY	1	1	1	1	4	2	2	16	2	1



STEP 1




STEP 2





STEP 3





STEP 4





STEP 5



STEP 6



STEP 7





ASSEMBLY INSTRUCTION

MODEL:MARE LN6916 2211EE



HARDWARE LIST

NO	A	B	C	D	E	F	G	H	I	J
DESC										
QTY	1	1	1	1	4	2	2	16	2	1



STEP 1




STEP 2





STEP 3





STEP 4





STEP 5



STEP 6



STEP 7





ASSEMBLY INSTRUCTION

MODEL:MARE 2211 LN6916

HARDWARE LIST

NO	A	B	C	D	E	F	G
DESC							
QTY	1	1	1	2	2	16	1

STEP 1



STEP 2

